

Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5

Add a Command --300




Fig. 6




Fig. 7




Fig. 8




Fig. 9





Fig. 10

```
Edit Handler Custos Code
  New Custom Code
   excern ALSTATUS
                                                                                                Close
  WD_CommandSHandler(cil_env *pCliknw, paraskist *pParane, shyte *phuxBut)
       PLSTATUS
                    status = OK;
                    *pVall:
       abyte
       parambeser *pFarambeser1;
                     *pVal2 = WULL;
       sbyte
       parambescr *pParambescr2;
                                                                                                 Revert
       / get required parameter */
       status - RCC_DB_RetrieveParam(pParams, NVLL, aCommand3_NVLL1, apParambesc
       at ( OK '- status )
            return(status);
       } wise pWmil = (abyte*)(pFermsfercri**pWmius);
       RCC_EXT_WeiseStr(pClillnu, bCommandSHagNaquiradValua);
       PCC_PXT_UniveSurLine(pCliInv, pVall);
       /* get optional parameter */
if (OK == RCC_DB_PetrieweParam(pParame, NULL, mCommand3_NULL2, apparambes
            pval2 = (sbyte*)(pParaaDescr2-*pValue);
            PCC_EXT_WriteStr(pCliffry, hCcammad3MsgOpthonalValue);
PCC_EXT_WriteStrtine(pCliffry, pVal3);
```

600

Fig. 11






Fig. 14 720 **Quick Command Export** Export Selection: 721 Export -Insert Command Node Help String (HS=) 🔽 Command Name (C=) SetAll ✓ Help Handler (HH=) No Form (NO) Cancel Clear All ▼ Access (AC=) ▼ Rapid Mark (RM=) Prompt String (PS=) -Insert Parameter 722 ▼ Access (AC=) ▼ Parameter Name (P=) SetAll ▼ Validate String (VS=) UnNamed (P=NULL) Clear All Type (TP=) ▼ Rapid Mark (RM=) ▼ Valid Handler (VH=) ✓ Help String (HS=) ✓ Help Handler (HH=) Convert Native (CV) ▼ Notes (NT=) ▼ Default Value (DV=) 723 Insert Handler ▼ Handler Name (H=) ✓ No Form (ND) Set All ▼ Req. Param (RP=) Clear All - 🔽 Opt Param (OP=) Export File: Select File c:\demo\export.cli




Fig. 15